


Regarding Quality Control Certificate

Name of Work: Improvements to Road and Drains at Ayyappa Layout in Ward No:06, Dasarahalli Village Limits

Job No: 006-14-000031

Work Order No: / 21-02-2014

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT & H at this stage is not feasible since this work was executed ²----- Year back.


Executive Engineer

Byatarayanapura Division
Bruhat Bangalore Mahanagara Palike